

## Fire Damaged Generator



### ILC Assignment:

- Desk review of a loss event in which a CAT 3516 generator set reportedly caught fire.
- Inspect equipment and review the costs submitted by the insured to determine if they are in line with the claimed damage.
- Determine if the generator required any additional work to return the equipment to pre-loss condition.
- If additional work is required, determine the scope of work to be completed and the timeframe.

### ILC Analysis:

- ILC thoroughly inspected the damaged equipment to determine if it was restorable to pre-loss condition.
- ILC acquired documentation and reviewed the repair services and costs that were completed.
- ILC verified the vendor's additional recommended costs of repairs and labor of \$5,900 as reasonable in returning the equipment to pre-loss condition.

### Summary:

- ILC's thorough inspection of the insureds' loss revealed that the vendors used LKQ parts to accomplish the repairs.
- ILC recommended the inclusion of the additional \$5,900 to achieve pre-loss condition.