

MRI Water Damage Loss



ILC Assignment:

- Inspect Siemens MRI to determine extent of damage.
- Determine if the MRI is restorable to pre-loss condition.
- Review repair estimate from OEM to determine if it is accurate.
- Arrange for independent repair quote to bring MRI to pre-loss condition.

ILC Inspection Details:

- The OEM had already inspected this MRI.
- The OEM estimate listed repairs totaling \$108,000.00.
- ILC inspected the MRI on site. ILC completed a full diagnostic sweep of the MRI functionality.
- ILC organized an independent qualified inspection documenting a significantly reduced repair estimate.
- With the assistance of ILC this claim of \$108,000.00 was reduced to \$6,000.00.

Summary:

- Loss reduction of \$102,000.00.
- Any Original Equipment Manufacturer (OEM) must be independently verified for accuracy.
- Immediate inspection of loss site was critical to prevent further loss damages.